

39107, Revision No. 1, dated December 13, 2017.

TABLE 1 TO PARAGRAPH (g)—COMPLIANCE TIME REQUIREMENTS

	Compliance time [A or B, whichever occurs later after the effective date of this AD]
A .....	Before the FCU accumulates 1,500 flight hours, or before the FCU accumulates six years since new or last overhaul, whichever occurs first.
B .....	Within six months.

**(h) Credit for Previous Actions**

You may take credit for the replacement of the FCU that is required by paragraph (g) of this AD if you replaced the FCU with an FCU that incorporates a stainless steel air adapter before the effective date of this AD using P&WC SB No. PT6B-72-39107, Original Issue, dated December 15, 2016.

**(i) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, ECO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the ECO Branch, send it to the attention of the person identified in paragraph (j)(1) of this AD. You may email your request to: *ANE-AD-AMOC@faa.gov*.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

**(j) Related Information**

(1) For more information about this AD, contact Mehdi Lamnyi, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA, 01803; phone: 781-238-7743; fax: 781-238-7199; email: *Mehdi.Lamnyi@faa.gov*.

(2) Refer to Transport Canada Civil Aviation (Transport Canada) AD CF-2019-05, dated February 19, 2019, for more information. You may examine the Transport Canada AD in the AD docket on the internet at *https://www.regulations.gov* by searching for and locating it in Docket No. FAA-2020-0471.

(3) For service information identified in this AD, contact Pratt & Whitney Canada Corp., 1000 Marie-Victorin, Longueuil, Quebec, Canada, J4G 1A1; phone: 800-268-8000; fax: 450-647-2888; website: *https://www.pwc.ca/en/*. You may view this referenced service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call 781-238-7759.

Issued on May 5, 2020.

**Lance T. Gant,**

Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2020-09944 Filed 5-13-20; 8:45 am]

**BILLING CODE 4910-13-P**

**DEPARTMENT OF TRANSPORTATION**

**Federal Aviation Administration**

**14 CFR Part 39**

**[Docket No. FAA-2020-0472; Product Identifier 2018-CE-060-AD]**

**RIN 2120-AA64**

**Airworthiness Directives; Textron Aviation Inc. Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for all Textron Aviation Inc. (Textron) Models 180, 180A, 180B, 180C, 180D, 180E, 180F, 180G, 180H, 180J, 180K, 182, 182A, 182B, 182C, 182D, 185, 185A, 185B, 185C, 185D, 185E, A185E, and A185F airplanes. This proposed AD was prompted by a report of cracks found in the tailcone and horizontal stabilizer attachment structure. This proposed AD would require inspecting the tailcone and horizontal stabilizer for corrosion and cracks and repairing or replacing damaged parts as necessary. The FAA is proposing this AD to address the unsafe condition on these products.

**DATES:** The FAA must receive comments on this proposed AD by June 29, 2020.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to *https://www.regulations.gov*. Follow the instructions for submitting comments.
- *Fax:* 202-493-2251.
- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.
- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this NPRM, contact Textron Aviation Customer Service, P.O. Box 7706,

Wichita, Kansas 67277, (316) 517-5800; *customercare@txtav.com*; *https://txtav.com*. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

**Examining the AD Docket**

You may examine the AD docket on the internet at *https://www.regulations.gov* by searching for and locating Docket No. FAA-2020-0472; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:** Tara Shawn, Aerospace Engineer, Wichita ACO Branch, 1801 Airport Road, Room 100, Wichita, Kansas 67209; telephone: (316) 946-4141; fax: (316) 946-4107; email: *tara.shawn@faa.gov* or *Wichita-COS@faa.gov*.

**SUPPLEMENTARY INFORMATION:**

**Comments Invited**

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2020-0472; Product Identifier 2018-CE-060-AD” at the beginning of your comments. The FAA specifically invites comments on the overall regulatory, economic, environmental, and energy aspects of this NPRM. The FAA will consider all comments received by the closing date and may amend this NPRM because of those comments.

The FAA will post all comments received, without change, to *https://www.regulations.gov*, including any personal information you provide. The FAA will also post a report

summarizing each substantive verbal contact received about this NPRM.

**Discussion**

The FAA received a report of cracks in the tailcone and horizontal stabilizer attachment structure on a Textron (type certificate previously held by Cessna Aircraft Company) Model 185 airplane. It was observed during maintenance that the horizontal stabilizer tail section moved up and down and had excessive play. After a detailed inspection, the tailcone reinforcement braces were found cracked on both sides of the airplane. Upon further investigation, the FAA discovered similar conditions on 29 additional Textron 180 and 185 series airplanes. The FAA determined that the combination of the attachment structure design and high loads during landing contribute to the development of cracks in the tailcone and horizontal stabilizer attachment structure. This condition, if unaddressed, could result in failure of the horizontal stabilizer to tailcone attachment and lead to tail

separation with consequent loss of control of the airplane.

**Related Service Information Under 1 CFR Part 51**

The FAA reviewed Textron Aviation Single Engine Mandatory Service Letter SEL-55-01, dated December 7, 2017. The service information contains procedures for inspecting the stabilizer hinge brackets, tailcone reinforcement angles, corner reinforcements, stabilizer hinge reinforcement channel, stabilizer hinge assemblies, stabilizer aft spar reinforcement, and the lower half of the stabilizer aft spar from station (STA) 16 on the left side of the stabilizer aft spar to STA 16 on the right side for cracks and corrosion. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

**FAA's Determination**

The FAA is proposing this AD because it evaluated all the relevant information and determined the unsafe

condition described previously is likely to exist or develop in other products of the same type design.

**Proposed AD Requirements**

This proposed AD would require accomplishing the actions specified in the service information described previously.

**Differences Between This Proposed AD and the Service Information**

The service information applies to airplanes with more than 3,000 total hours time-in-service or 10 years in service, while this proposed AD would apply regardless of the airplane's time-in-service. This proposed AD would require inspecting for and replacing loose or sheared rivets, which is not specified in the service information.

**Costs of Compliance**

The FAA estimates that this proposed AD would affect 6,586 airplanes of U.S. registry.

The FAA estimates the following costs to comply with this proposed AD:

**ESTIMATED COSTS**

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspection .....	2 work-hours × \$85 per hour = \$170 .....	Not applicable .....	\$170	\$1,119,620

The FAA estimates the following costs to do any necessary replacements that would be required based on the

results of the proposed inspection. The FAA has no way of determining the

number of aircraft that might need these actions:

**ON-CONDITION COSTS**

Action	Labor cost	Parts cost	Cost per product
Replace left-hand (LH) stabilizer hinge bracket .....	4 work-hours × \$85 per workhour = \$340 .....	\$551	\$891
Replace right-hand (RH) stabilizer hinge bracket .....	4 work-hours × \$85 per workhour = \$340 .....	530	870
Replace LH tailcone reinforcement angle .....	12 work-hours × \$85 per workhour = \$1,020 .....	2,291	3,311
Replace RH tailcone reinforcement angle .....	12 work-hours × \$85 per workhour = \$1,020 .....	3,006	4,026
Replace LH corner reinforcement .....	6 work-hours × \$85 per workhour = \$510 .....	169	679
Replace RH corner reinforcement .....	6 work-hours × \$85 per workhour = \$510 .....	390	900
Replace LH stabilizer hinge reinforcement channel ....	6 work-hours × \$85 per workhour = \$510 .....	99	609
Replace RH stabilizer hinge reinforcement channel ....	6 work-hours × \$85 per workhour = \$510 .....	99	609
Replace LH stabilizer hinge assembly .....	1 work-hours × \$85 per workhour = \$85 .....	570	655
Replace RH stabilizer hinge assembly .....	1 work-hours × \$85 per workhour = \$85 .....	694	779
Replace LH stabilizer aft spar reinforcement .....	* .....	825	825
Replace RH stabilizer aft spar reinforcement .....	* .....	466	466
Replace stabilizer aft spar (* includes work-hour cost for replacing stabilizer aft spar reinforcement parts).	28* work-hours × \$85 per workhour = \$2,380 .....	563	2,943
Remove and replace horizontal and vertical stabilizers and rig flight controls.	8 work-hours × \$85 per workhour = \$680 .....	(*)	680

\* Not applicable.

Since corrosion may affect any or all of the parts subject to the inspection in this proposed AD differently and the severity of the corrosion on each part would affect the time necessary to

correct the condition, the FAA has no way to determine an overall cost per product for removing the corrosion. Similarly, loose or sheared rivets may also affect any or all of the parts subject

to the inspection in this proposed AD differently, and the time necessary to correct the condition on each product would be different. Therefore, the FAA has no way to determine an overall cost

per product for replacing loose or sheared rivets.

### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

### Regulatory Findings

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

### PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

### § 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**Textron Aviation Inc.:** Docket No. FAA–2020–0472; Product Identifier 2018–CE–060–AD.

#### (a) Comments Due Date

The FAA must receive comments by June 29, 2020.

#### (b) Affected ADs

None.

#### (c) Applicability

This AD applies to Textron Aviation Inc. (type certificate previously held by Cessna Aircraft Company) Models 180, 180A, 180B, 180C, 180D, 180E, 180F, 180G, 180H, 180J, 180K, 182, 182A, 182B, 182C, 182D, 185, 185A, 185B, 185C, 185D, 185E, A185E, and A185F airplanes, all serial numbers, certificated in any category.

#### (d) Subject

Joint Aircraft System Component (JASC)/ Air Transport Association (ATA) of America Code 53, Fuselage; 55, Stabilizers.

#### (e) Unsafe Condition

This AD was prompted by a report of cracks found in the tailcone and horizontal stabilizer attachment structure. The FAA is issuing this AD to detect and correct corrosion and cracks in the tailcone and horizontal stabilizer attachment structure. The unsafe condition, if not addressed, could result in failure of the horizontal stabilizer to tailcone attachment, which could lead to tail separation with consequent loss of control of the airplane.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Inspect, Repair, and Replace

Within the next 100 hours time-in-service (TIS) after the effective date of this AD or within the next 12 months after the effective date of this AD, whichever occurs later, and thereafter every 500 hours TIS or 5 years, whichever occurs first, visually inspect each stabilizer hinge bracket, tailcone reinforcement angle, corner reinforcement, stabilizer hinge reinforcement channel, stabilizer hinge assembly, stabilizer aft spar reinforcement, and the lower half of the stabilizer aft spar from station (STA) 16 on the left side to STA 16 on the right side for corrosion and cracks; remove any corrosion; and replace any part with a crack by following the Accomplishment Instructions, paragraphs 9 through 11 and 13, of Textron Aviation Single Engine Mandatory Service Letter SEL–55–01, dated December 7, 2017. Also inspect for loose rivets and sheared rivets. If there is a loose or sheared rivet, before further flight, replace the rivet.

#### (h) Credit for Previous Actions

Actions accomplished before the effective date of this AD within the previous 5 years or 500 hours TIS, whichever was the most

recent, in accordance with the procedures specified in the documents listed in paragraphs (h)(i) through (viii) of this AD as applicable to your airplane are considered acceptable for compliance with the corresponding actions in paragraph (g) of this AD. The time between any inspection for which credit is allowed by this paragraph and the next inspection accomplished in accordance with paragraph (g) of this AD must not exceed 500 hours TIS or 5 years, whichever occurs first.

(i) Cessna Aircraft Company Model 100 Series (1953–1962) Service Manual, Supplemental Inspection Number: 53–10–01, D138–1–13 Temporary Revision Number 8, dated May 18, 2015.

(ii) Cessna Aircraft Company Model 100 Series (1963–1968) Service Manual, Supplemental Inspection Number: 53–10–01, D637–1–13 Temporary Revision Number 10, dated May 18, 2015;

(iii) Cessna Aircraft Company Model 180/185 Series (1969–1980) Service Manual, Supplemental Inspection Number: 53–10–01, D2000–9–13 Temporary Revision Number 9, dated May 18, 2015.

(iv) Cessna Aircraft Company Model 180/185 Series (1981–1985) Service Manual, Supplemental Inspection Number: 53–10–01, D2067–1TR9 Temporary Revision Number 9, dated May 1, 2016.

(v) Cessna Aircraft Company Model 100 Series (1953–1962) Service Manual, Supplemental Inspection Number: 53–10–01, D138–1–13 Temporary Revision Number 7, dated December 1, 2011.

(vi) Cessna Aircraft Company Model 100 Series (1963–1968) Service Manual, Supplemental Inspection Number: 55–10–01, D637–1–13 Temporary Revision Number 9, dated December 1, 2011.

(vii) Cessna Aircraft Company Model 180/185 Series (1969–1980) Service Manual, Supplemental Inspection Number: 55–10–01, D2000–9–13 Temporary Revision Number 7, dated December 1, 2011.

(viii) Cessna Aircraft Company Model 180/185 Series (1981–1985) Service Manual, Supplemental Inspection Number: 55–10–01, D2067–1–13 Temporary Revision Number 7, dated December 1, 2011.

#### (i) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Wichita ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local

Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j) of this AD.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

#### (j) Related Information

(1) For more information about this AD, contact Tara Shawn, Aerospace Engineer, Wichita ACO Branch, 1801 Airport Road,

Room 100, Wichita, Kansas 67209; telephone: (316) 946-4141; fax: (316) 946-4107; email: [tara.shawn@faa.gov](mailto:tara.shawn@faa.gov) or [Wichita-COS@faa.gov](mailto:Wichita-COS@faa.gov).

(2) For service information identified in this AD, contact Textron Aviation Customer Service, P.O. Box 7706, Wichita, Kansas 67277, (316) 517-5800; [customercare@txtav.com](mailto:customercare@txtav.com); <https://txtav.com>. You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

Issued on May 8, 2020.

**Gaetano A. Sciortino,**

*Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.*

[FR Doc. 2020-10316 Filed 5-13-20; 8:45 am]

BILLING CODE 4910-13-P

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2020-0473; Product Identifier 2018-CE-058-AD]

RIN 2120-AA64

#### Airworthiness Directives; Polskie Zaklady Lotnicze Sp. z o.o. Airplanes

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for certain Polskie Zaklady Lotnicze Sp. z o.o. Model PZL M28 05 airplanes. This proposed AD results from mandatory continuing airworthiness information (MCAI) originated by an aviation authority of another country to identify and correct an unsafe condition on an aviation product. The MCAI describes the unsafe condition as defective thermo-shrinkable tubes installed on the electrical harnesses located in the fuel tanks. The FAA is proposing this AD to address the unsafe condition on these products.

**DATES:** The FAA must receive comments on this proposed AD by June 29, 2020.

**ADDRESSES:** You may send comments by any of the following methods:

- *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* (202) 493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this proposed AD, contact Polskie Zaklady Lotnicze Sp. z o.o., Wojska Polskiego 3, 39-300 Mielec, Poland, +48 17 743 1901, email: [pzl.lm@lmco.com](mailto:pzl.lm@lmco.com), internet: [www.pzlmielec.pl](http://www.pzlmielec.pl). You may review this referenced service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 901 Locust, Kansas City, Missouri 64106. For information on the availability of this material at the FAA, call (816) 329-4148.

#### Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0473; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this proposed AD, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:** Doug Rudolph, Aerospace Engineer, FAA, Small Airplane Standards Branch, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4059; fax: (816) 329-4090; email: [doug.rudolph@faa.gov](mailto:doug.rudolph@faa.gov).

#### SUPPLEMENTARY INFORMATION:

##### Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposed AD. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA-2020-0473; Product Identifier 2018-CE-058-AD” at the beginning of your comments. The FAA specifically invites comments on the overall regulatory, economic, environmental, and energy aspects of this proposed AD. The FAA will consider all comments received by the closing date and may amend this proposed AD because of those comments.

The FAA will post all comments we receive, without change, to <https://www.regulations.gov>, including any personal information you provide. The FAA will also post a report summarizing each substantive verbal contact received about this proposed AD.

#### Discussion

The European Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued AD No. 2018-0242, dated October 8, 2018 (referred to after this as “the MCAI”), to correct an unsafe condition for the specified products. The MCAI states:

During accomplishment of maintenance on an M28 05 military version airplane, torn pieces of thermo-shrinkable tubes were found in the header section of the main fuel tank. These tubes are installed on electrical harnesses located in the fuel tanks and serve as marking and protection devices against mechanical damage during manufacturing and servicing. Pieces of these tubes may travel with the fuel flow and may block the jet pump or reduce its performance, particularly in the centre-wing fuel tank, in which the jet pump is the only way of further transfer of fuel to the engine. Subsequent investigation determined that degradation of the tube material was caused by a manufacturing deficiency, leading to insufficient material resistance against mechanical damage when a tube is located in a fuel.

This condition, if not detected and corrected, could lead to reduced fuel supply to the engines, inability to use all the fuel in fuel tanks and reduced available engine power, resulting in reduced aeroplane performance.

To address this potentially unsafe condition, PZL identified the batch of aeroplanes that are potentially equipped with thermo-shrinkable tubes having this manufacturing defect, and issued the [service bulletin] SB providing inspection and replacement instructions.

For the reasons described above, this [EASA] AD requires a one-time inspection of the electrical harnesses located in the fuel tanks and, depending on findings, replacement of the affected harness.

Polskie Zaklady Lotnicze Sp. z o.o. informed us the potential for damage to the thermo-shrinkable tubes does not progress with time. Therefore, we determined repetitive inspections are not required. You may examine the MCAI on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0473.

#### Related Service Information Under 14 CFR Part 51

Polskie Zaklady Lotnicze Sp. z o.o. has issued Service Bulletin No. E/12.141/2018, dated May 15, 2018. The service information contains procedures for inspecting the thermo-shrinkable tubes on the electrical harnesses in the center and outer wing fuel tanks for damage and replacing any electrical harness with damaged thermo-shrinkable tubes. This service information is reasonably available